
H602





Installation Manual:

- 1 J The Ø20mm PVC tube for AC 220V Power wires(3 X Ø2.0mm).
- The tube for connecting vice-machine to master machine in the same lane (CAT5 network cables*2PCS, 2 * 0.5mm motor line*1PCS). 2
- TCP/IP ethernet cable for connecting access device to PC. 3
- Control board . 4 0
- Fixing the equipment with M12 X 100mm expansive bolt . 5

Mark: All wires extending out of the ground shall be no less than 2M.



